

100

DEFINE CRITICAL OR
PHASE SHIFT DEFINED
POLY, CREATE PHASE
REGIONS ON EITHER SIDE,
AND ASSIGN PHASE
ANGLES TO REGIONS

110

DEFINE REMAINING POLY
EDGES AND JOIN EDGES
TO ASSIGNED AREAS

120

DEFINE BOUNDARY
AROUND EDGES

130

DEFINE AREA OUTSIDE
THE BOUNDARY AS
PHASE ZERO


140

CURE DESIGN RULE
VIOLATION AREAS AND
APPLY CORRECTION
PROCEDURES

150

FIG. 1

10015439.13101
TOP SECRET 6249001



300




FIG. 3




FIG. 4

